



Adjust R5, R18 depending on desired output current for good trim resolution
 Add R2, R3 for additional standby suppression hysteresis

Jan Weigelt <jan@jan-weigelt.com>

Sheet: /
 File: ld_driver.sch

Title: LD Driver

Size: A4 Date: 2019-09-16

KiCad E.D.A. kicad 4.0.7

Rev: 1

Id: 1/1